Paste dries out over years, so an older HP throttles earlier https://repairhouse.co.ke/brand/hp/ than it should. Repasting restores most of the original thermal headroom for a modest cost. Repasting at %LINK%.